



Set up RTC timer for automatic start of Ultron

- Turn on Ultron and press DELETE to enter bios
- Then go into Advanced, followed by S5 RTC Wake Settings



- Set Wake System from S5 to Fixed Time and select time



- After selection, press F10 and select YES

Set up shutting down Ultron in Windows using Command Prompt

- Start a command prompt with administrator rights and enter the following:
18:00 (Marked in red, can be changed to the desired turn-off time)

```
schtasks /CREATE /SC DAILY /TN "SHUTDOWN" /TR "C:\Windows\System32\shutdown.exe /s /f" /ST 18:00
```

Further customization / changes must then be customized in the Windows task manager